


1000 Ohms

Gnd(common cathode)






bend to ~45 degree




separate the legs with the resistor









trim two legs


solder 4 legs



centered



trim to the shortest residue







final effect