

Release Note

General information	
Solution	UK DTM (Ocious) – T-Protocol
Summary of Key Changes	Defects, Features and Cosmetic.
Hardware platforms supported	P400, V240m, V200c, E285
New Software Version	2.10.0.43
Previous Software Version	2.10.0.38
OS Version	31014000
ADK Version	4.6.42
Release Date	15/04/2026
Released by	EMEA ADC

Upgrade Process.

Verifone highly recommends that all software updates are to be done during the maintenance window as set in the terminals. The maintenance window unless changed 22:00 – 06:00 unless changed via Webcom. If updates are deployed outside of this window then merchants should allow 1 hour for updates to occur and during this time the terminal must be left alone. This is to ensure successful completion of the updates.

You must be running a version between 2.10.0.26 and 2.10.0.38 before upgrading to 2.10.0.43, due to the change in the ADK component of the software.

#	Released Items	Type
1	Added in support for auto renewal of VRK (transaction encryption) keys, when they become exhausted. The keys will be auto renewed within 24 hours of expiry.	Feature
2	AEUKOCE-30252 – Added support for deferred authorisation.	Feature
3	AEUKOCE-29925 – Routine upgrade of the ADK to the latest 4.6.42	Feature
4	AEUKOCE-29978 – Added support for Online Refund.	Feature
5	ENT-29930 – Corrected logic around Capital One Cards, to prevent some cards being rejected.	Defect
6	ENT-23970 – Corrected logic around incorrect xml tags for token registration only, to ensure that the <TokenRegistrationOnly>false</TokenRegistrationOnly> is true, not false.	Defect
7	AEUKOCE-30469 – Corrected offline processing of Diners/Discover cards when the terminal is in an offline state.	Defect
8	AEUKOCE-29761 - Corrected integration comms to prevent the terminal from hanging on Submitting Offline Transactions, post upload of the transactions.	Defect
9	AEUKOCE-29871 – Corrected data storage of SVS transactions to prevent transactions becoming stuck offline.	Defect
10	AEUKOCE-30106 – Corrected defects in the terminal logic to allow for the network interface to be able to be set via the terminal menus.	Defect
11	AEUKOCE-30108 – Removed the green tick on the contactless transaction flow when additional interaction is required on the cardholders phone to remove any confusion.	Defect
12	AEUKOCE-30118 – Removed the additional colon on the sale screen for SVS transactions for the available balance.	Cosmetic Change

End of Document